



NOWD Testing Services Co., Ltd.

TEL: +86-755-2783 0065 FAX: +86-755-2783 0095

ADD: 5A, Building 29B, Yintian Industrial Zone, Yantian Community,
Xixiang Street, Bao'an District, Shenzhen, China

Email: nowd@nowd.com.cn

Web: http://www.nowd.com.cn

Verification of Compliance

Reference No. : NTS2307077
Report No. : NTS2307077S, NTS2307078E
Applicant : **Shenzhen Hengketong Robot Co., Ltd**
1702, Building 4, Tian'an Yungu Phase 2, Longgang District, Shenzhen,
China
Manufacture : **Shenzhen Hengketong Robot Co., Ltd**
1702, Building 4, Tian'an Yungu Phase 2, Longgang District, Shenzhen,
China
Product : Low Voltage Servo Motor
Model No. : TD6040-SCANK5-1, (others refer to appendix)
Trade Mark : N/A

The submitted sample of the above equipment has been tested for CE marking according to the following European Directives:

LVD Directive:	2014/35/EU
EMC Directive:	2014/30/EU

Standard(s) used for showing compliance with the essential requirements in the specified directive(s):

Test Standards	EN 60034-1: 2010	EN IEC 61000-3-2: 2019+A1:2021
	EN IEC 61000-6-1: 2019	EN 61000-3-3: 2013+ A1: 2019+A2:2021
	EN IEC 61000-6-3: 2021	

The statement is based on a single evaluation of one sample of above mentioned products. It does not imply an assessment of the whole production.

The manufacture should ensure that all products in series production are in conformity with the product sample detailed in this report. The applicant should hold the whole technical report at disposal of the competent all the right.



Signed for and on behalf of
NOWD Testing Services Co., Ltd.

Somnus

Technical Manager

Date: August 03, 2023



NOWD Testing Services Co., Ltd.

TEL: +86-755-2783 0065 **FAX:** +86-755-2783 0095

ADD: 5A, Building 29B, Yintian Industrial Zone, Yantian Community,
Xixiang Street, Bao'an District, Shenzhen, China

Email: nowd@nowd.com.cn

Web: <http://www.nowd.com.cn>

Appendix for NTS2307077

Reference No. : NTS2307077
Product : Low Voltage Servo Motor
Model No. : TD6040-SCANK5-1,



TD4005-SCABK5-1, TD4005-SCANK5-1, TD4005-SCBBK5-1,
TD4005-SCBNK5-1, TD4005-MCABK5-1, TD4005-MCANK5-1,
TD4005-MCBBK5-1, TD4005-MCBNK5-1, TD4010-SCABK5-1,
TD4010-SCANK5-1, TD4010-SCBBK5-1, TD4010-SCBNK5-1,
TD4010-MCABK5-1, TD4010-MCANK5-1, TD4010-MCBBK5-1,
TD4010-MCBNK5-1, TD6020-SCABK5-1, TD6020-SCANK5-1,
TD6020-SCBBK5-1, TD6020-SCBNK5-1, TD6020-MCABK5-1,
TD6020-MCANK5-1, TD6020-MCBBK5-1, TD6020-MCBNK5-1,
TD6040-SCABK5-1, TD6040-SCBBK5-1, TD6040-SCBNK5-1,
TD6040-MCABK5-1, TD6040-MCANK5-1, TD6040-MCBBK5-1,
TD6040-MCBNK5-1, TD6060-SCABK5-1, TD6060-SCANK5-1,
TD6060-SCBBK5-1, TD6060-SCBNK5-1, TD6060-MCABK5-1,
TD6060-MCANK5-1, TD6060-MCBBK5-1, TD6060-MCBNK5-1,
TD8075-SCABK5-1, TD8075-SCANK5-1, TD8075-SCBBK5-1,
TD8075-SCBNK5-1, TD8075-MCABK5-1, TD8075-MCANK5-1,
TD8075-MCBBK5-1, TD8075-MCBNK5-1, TD80100-SCABK5-1,
TD80100-SCANK5-1, TD80100-SCBBK5-1, TD80100-SCBNK5-1,
TD80100-MCABK5-1, TD80100-MCANK5-1, TD80100-MCBBK5-1,
TD80100-MCBNK5-1, TD13085-SDABK5-1, TD13085-SDANK5-1,
TD13085-SDBBK5-1, TD13085-SDBNK5-1, TD13085-MDABK5-1,
TD13085-MDANK5-1, TD13085-MDBBK5-1, TD13085-MDBNK5-1,
TD130130-SDABK5-1, TD130130-SDANK5-1, TD130130-SDBBK5-1,
TD130130-SDBNK5-1, TD130130-MDABK5-1, TD130130-MDANK5-1,
TD130130-MDBBK5-1, TD130130-MDBNK5-1, TD130150-SCABK5-1,
TD130150-SCANK5-1, TD130150-SCBBK5-1, TD130150-SCBNK5-1,
TD130150-MCABK5-1, TD130150-MCANK5-1, TD130150-MCBBK5-1,
TD130150-MCBNK5-1, TD130180-SDABK5-1, TD130180-SDANK5-1,
TD130180-SDBBK5-1, TD130180-SDBNK5-1, TD130180-MDABK5-1,
TD130180-MDANK5-1, TD130180-MDBBK5-1, TD130180-MDBNK5-1,
TD130200-SCABK5-1, TD130200-SCANK5-1, TD130200-SCBBK5-1,
TD130200-SCBNK5-1, TD130200-MCABK5-1, TD130200-MCANK5-1,
TD130200-MCBBK5-1, TD130200-MCBNK5-1